

Package Outline Dimension Table			
Symbol	Millimeters		
	Min.	Nom.	Max.
A	_	_	4.10
A1	0.25	_	0.50
A2	3.20	3.40	3.60
D	34.60 BSC		
D1	32.00 BSC		
E	34.60 BSC		
E1	32.00 BSC		
L	0.45	0.60	0.75
L1	1.30 REF		
S	0.20	_	_
b	0.17	_	0.27
С	0.09	_	0.20
→ e	0.50 BSC		
θ	0°	3.5°	8°

Detail A Gage Plane 0.25mm

What is the placement tolerance of symbol 'e' if the pin moves towards other pin?