

Intel® Driver & Support Assistant

Detailed Report

Last scan: 03/07/2019 14:51

Computer

IFSA Positivo BGH

System Manufacturer	IFSA
System Model	Positivo BGH
System Type	Mobile
Motherboard Manufacturer	AMI Corporation
Motherboard Product	T290
BIOS Version	5.6.5
SMBIOS Version	2.8
Secure Boot	On

Operating System

Microsoft Windows 10 Home Single Language (64 bits)

Version	1803
OS Build	10.0.17134
Build Branch	rs4_release
Locale	Español (Argentina)
Windows Directory	C:\WINDOWS
System Directory	C:\WINDOWS\system32
.NET Framework Versions	2.0.50727.4927, 3.0.30729.4926, 3.5.30729.4926, 3.5.30729.5003, 4.0.0.0, 4.7.03056
Default Internet Browser	Internet Explorer 11.829.17134.0
Installed Internet Browsers	Avast Secure Browser, Google Chrome, Internet Explorer 11.829.17134.0, SafeZone Stable

Processor

Intel® Celeron® CPU N2807 @ 1.58GHz

Manufacturer	GenuineIntel
Description	Intel64 Family 6 Model 55 Stepping 8

Architecture	x64
# of Cores	2
# of Threads	2
Processor Base Frequency	1578 MHz
Current Voltage	1.8
Level 2 Cache	1024 Kb
Level 3 Cache	0 Kb
Processor Id	0x30678
Revision	14088
Availability	Running at full power

Graphics

Intel® HD Graphics

Adapter Compatibility	Intel Corporation
Video Processor	Intel® HD Graphics
Resolution	1024 x 768
Bits Per Pixel	32
Number of Colors	4294967296
Refresh Rate - Current	60 Hz
Refresh Rate - Maximum	75 Hz
Refresh Rate - Minimum	59 Hz
Driver Provider	Intel Corporation
Driver Version	10.18.10.4358
Driver Date	21/12/2015
Adapter DAC Type	Internal
Adapter RAM	2,02 GB
Availability	Running at full power
Status	This device is working properly.
Location	PCI bus 0, device 2, function 0
Device Id	PCI\VEN_8086&DEV_0F31&SUBSYS_0F318086&REV_0E\3&11583659&0&10

Audio

Sonido Intel® para pantallas

Driver Provider	Intel® Corporation
Driver Version	6.16.0.3154
Driver Date	09/09/2014
Device Id	HDAUDIO\FUNC_01&VEN_8086&DEV_2882&SUBSYS_80860101&REV_1000\4&373B8910&0&0201

Realtek High Definition Audio

Driver Provider	Realtek Semiconductor Corp.
Driver Version	6.0.1.7083
Driver Date	11/05/2013
Device Id	HDAUDIO\FUNC_01&VEN_10EC&DEV_0269&SUBSYS_1D090101&REV_1001\4&373B8910&0&0001

Networking and I/O

Qualcomm Atheros AR9485WB-EG Wireless Network Adapter

Manufacturer	Qualcomm Atheros Communications Inc.
Availability	Running at full power
Status	This device is disabled.
Installed	True
Service Name	athr
Driver Provider	Microsoft
Driver Version	3.0.2.201
Driver Date	26/03/2016
Device Id	PCI\VEN_168C&DEV_0032&SUBSYS_2C971A3B&REV_01\4&5BC483&0&00E0
Revision	01

Realtek PCIe FE Family Controller

Manufacturer	Realtek
Availability	Running at full power
Status	This device is working properly.
Installed	True
MAC Address	30:F7:D7:00:5A:EB
Service Name	rt640x64
Driver Provider	Microsoft

Driver Version	9.1.406.2015
Driver Date	04/06/2015
Device Id	PCI\VEN_10EC&DEV_8136&SUBSYS_813610EC&REV_05\4&1CEE7D5C&0&00E1
Revision	05

Memory

4 GB

Physical Memory - Total	4 GB
Physical Memory - Available	1,52 GB
Virtual Memory - Total	4,70 GB
Virtual Memory - Available	1,85 GB
Page File	C:\pagefile.sys
Page File Space	0,79 GB

Storage

TOSHIBA MQ01ABF050

Capacity	465,76 GB
Firmware Version	AM0P1A
Serial Number	Y4CKCRTTT
Partitions	5
Driver Provider	Microsoft
Driver Version	10.0.17134.1
Driver Date	21/06/2006
Device Id	SCSI\DISK&VEN_TOSHIBA&PROD_MQ01ABF050\4&9D4E02E&0&000000

C:

File System	NTFS
Compressed	False
Capacity	449,76 GB
Free Space	376,79 GB
